

## **POOR LEGIBILITY**

ONE OR MORE PAGES IN THIS DOCUMENT ARE DIFFICULT TO READ  
DUE TO THE QUALITY OF THE ORIGINAL



HAZARDOUS  
SITE CONTROL  
DIVISION

**Remedial  
Planning/  
Field  
Investigation  
Team  
(REM/FIT)**

**ZONE II**

CONTRACT NO.  
68-01-6692

CH<sub>2</sub>M  HILL  
Ecology &  
Environment

SFUND RECORDS CTR  
88205128

CERCLA Site Inspection

Levin-Richmond Terminal Corp.  
Parr Canal Site  
8th Street and Wright Avenue  
Richmond, CA 94804  
Contra Costa County

SFUND RECORDS CTR  
3737-00067

**ecology and environment, inc.**

120 HOWARD STREET, SUITE #640, SAN FRANCISCO, CALIFORNIA 94105, TEL. 415-777-2811

International Specialists in the Environment

**AR0076**

Purpose: CERCLA Site Inspection

Site: Levin-Richmond Terminal Corp.  
Parr Canal Site  
8th Street and Wright Avenue  
Richmond, CA 94804  
Contra Costa County

SFUND RECORDS CTR  
3737-00067

Site ERRIS ID Number: CAD981436363

Inspection ID Number: C(86)215

TDD Number: R9-8609-01

FIT Investigators: Douglas D. Russell  
Mike Grant

Date of Inspection: August 14, 1986

Report Prepared by: Douglas D. Russell

Report Date: September 30, 1986

FIT Review :

*Patty Cook, 9-30-86*

## TABLE OF CONTENTS

1	<u>INTRODUCTION</u>	1-1
2	<u>SITE CHARACTERIZATION</u>	2-1
	2.1 <u>Site History and Description</u>	2-1
	2.2 <u>Sources of Contamination</u>	2-3
	2.3 <u>Contamination Investigations</u>	2-3
	2.4 <u>Permits</u>	2-6
	2.5 <u>Remedial Action</u>	2-7
3	<u>ENVIRONMENTAL SETTING</u>	3-1
	3.1 <u>Surrounding Area</u>	3-1
	3.2 <u>Geology</u>	3-1
	3.3 <u>Hydrology</u>	3-1
	3.3.1 <u>Surface Water</u>	3-1
	3.3.2 <u>Groundwater</u>	3-1
4	<u>SUMMARY OF FIT INVESTIGATIVE EFFORTS</u>	4-1
5	<u>HRS FACTORS</u>	5-1
6	<u>OTHER AGENCY INVOLVEMENT</u>	6-1
7	<u>CONCLUSIONS</u>	7-1
8	<u>RECOMMENDATIONS</u>	8-1
9	<u>REFERENCES</u>	9-1

### Appendices

- A Site Inspection Report Form
- B Contact Logs and Reports
- C Photo Documentation
- D Additional Information

## FIGURES AND TABLES

### Figures

- 1 Site Location Map ..... 1-2
- 2 Parr Canal Site Map ..... 2-2

### Tables

- 1 Summary of HLA Parr Canal Sample Results ..... 2-4



## 1 INTRODUCTION


The Levin-Richmond Terminal Corporation (LRTC) Parr Canal site is located at the southwest corner of the intersection of Wright Avenue and Eighth Street in Richmond, California (see Figure 1, Site Location Map). The property is bounded by Wright Avenue on the north, by Eighth Street on the east, by the Harbor Channel on the south, and by Time Oil Co. (CAD009602343) on the west. It is a 9.5-acre vacant lot which is bisected north to south by the Parr Canal which has a surface area of approximately 2.5 acres.

Little is known about the ownership and occupant history of this property. The site was apparently used as part of one of the Kaiser shipyards during the 1940s. Since then, the site seems to have been occupied by several smaller businesses, and may also have been used as a storage facility for scrap metal. The FIT file reviews revealed sketchy, sometimes conflicting information on the previous occupants and owners of this site.

Sampling by various agencies has shown the site to have been contaminated with DDT, PCBs, asbestos, and heavy metals. The source of most of these contaminants is unknown. However, it has been reported that DDT-contaminated material was disposed of at this site.

On August 1, 1986, Ecology and Environment's Field Investigation Team (FIT) submitted a Preliminary Assessment (PA) on the LRTC to the EPA. EPA had instructed FIT to conduct this PA due to increased public awareness of possible site contamination, triggered by newspaper articles. After the PA was submitted, EPA recommended that FIT conduct a Site Inspection, due to the extent of contamination believed to be on-site, and due to the potential for exposure to the public and to waters of the Bay.

The purpose of this report is to summarize information gained from FIT investigative efforts as well as from pertinent agencies. Recommendations for further action are also provided with regard to the LRTC/Parr Canal site. The FIT contacted several federal, state, local, and private agencies and persons for information pertaining to this site.



# **FIGURE 1** **Site Location Map**

**Levin Richmond/Parr Canal Site**

**Eighth and Wright Avenue  
Richmond, CA 94904  
Contra Costa County**

SCALE 1:24000



QUADRANGLE LOCATION

Source: USGS "Richmond, CA" Quad.

ecolo and environment, inc.

## 2 SITE CHARACTERIZATION

### 2.1 Site History and Description

LRTC is a subsidiary of Levin Metals Corporation whose headquarters are in San Jose, CA. Levin Metals runs scrap-metal salvage operations in Richmond, Sacramento, Stockton, and San Jose. The firm also maintains a metal sales center in Santa Clara, CA, and has other subsidiary companies dealing with metals.

The LRTC was formed in May, 1981 when Levin Metals bought the properties along the Lauritzen and Parr Canals from the Parr Richmond Terminal Corporation (see Figure 1). Parr Richmond Terminal Corporation acquired these properties from Parr Industrial Corporation in 1961, which in turn acquired the site around 1947. From 1940 to 1947, the area is believed to have been occupied by one of the Kaiser shipyards used in the Government's wartime shipbuilding effort. The site ownership history from 1925 to 1940 is unknown. However, a document found in the DOHS file, summarized here, gives some clues to pre-1940 site history: Parr Canal is a geologically old channel connected to San Pablo Bay which was filled in by railroad companies in the late 1800s. Part of the land was apparently owned by the Richmond Navigation Company and part by Proctor and Gamble. Proctor and Gamble apparently leased land to a company called Permanente Metals until World War II, when the War Department took over the entire area. The land was apparently reclaimed from tidal marsh and mudflats and filled to its present elevation with earth and rock from the hills to the west (Refs. 4,14,& 15).

LRTC operates a bulk cargo terminal (consisting of the loading and unloading of bulk cargo from large ships) at 402 Wright Avenue (LRTC/United Heckathorn CAD980673560), which is adjacent to, but separate from, the Parr Canal site (CAD 981436363). From around 1947 to around 1965, several companies leased buildings at 402 Wright Avenue to manufacture and distribute pesticides. Apparently, hazardous material from the 402 Wright Avenue (United Heckathorn) site, as well as hazardous dredge material from the adjacent Lauritzen Canal, have been disposed of at the Parr Canal site.

The site consists of about 12 acres, 2.5 acres of which are taken up by the Parr Canal (see Figure 2). The Parr Canal is an extension of the Harbor Channel, which makes up the south border of the site (see Introduction for other site borders). The landward sides of the property are fenced, locked, and posted with "Warning-Hazardous Waste Storage Area" signs. As of September 23, 1986, there were no seaward signs with similar warnings. A large storm-sewer outfall draining areas adjacent to south Eighth Street empties into the north end of the Parr Canal.

During the early 1950s and possibly up to the mid 1960s, a small boat marina occupied the west shore of the Parr Canal. A map, dated around 1960 and obtained from California Department of Fish and Game (CDFG) files, shows several companies located



Figure 2




1,463,500 E

522,500 N

522,000 N

521,500 N

1,463,500 E





on-site. Besides the small boat marina, Eight Ball Trucking, Freese Barge, and Parr Terminal Wharf metal scrap yard were all shown on the site map. Prior to LRTC's remedial work on-site (see Remedial Action section), there were four small, unused wood-frame buildings, and two railroad spurs with railroad cars waiting to be scrapped. The entire site has low topographic relief and was covered with grasses, shrubs, and brush prior to LRTC's remedial work (Ref. 15).

## 2.2 Sources of Contamination

During pesticide manufacture and distribution at the United Heckathorn site from 1947 to 1965, losses of "active" ingredients were reported to be about one percent for dry materials and .75 percent for liquids (ref. 14). Liquid losses allegedly resulted from evaporation, and dry material losses allegedly resulted from wind dispersion and from adherence to containers. The plant reportedly handled about 500 tons of DDT a month and about 25 tons of other pesticides a month. Monthly losses calculated from the above quantities and percentages would be 10,000 pounds of DDT and around 500 pounds of other pesticides. The plant manager also reported one instance in which solvent was accidentally released due to an open valve (ref. 14).

Soil and Lauritzen Canal sediments from around the United Heckathorn site that were contaminated were apparently relocated to the Parr Canal site. Dredge material taken from the Lauritzen Canal was allegedly dumped at the Parr Canal site during the early 1960s. This material is believed to have been contaminated from operations at United Heckathorn, and was apparently used as fill around the Parr Canal. About 20 years later, during the fall of 1982, LRTC is said to have removed approximately 30 truckloads of soils and asphalt from the United Heckathorn site to the Parr Canal site. Apparently, this material was placed in stockpiles on the eastern half of the Parr Canal site (Ref. 15). There is no evidence of other hazardous material having been dumped on the Parr Canal site.

## 2.3 Contamination Investigations

On October 1, 1981, David Belk of the California Department of Health Services (DOHS) responded to an anonymous tip about three on-site ponds. Belk did not find evidence of the ponds but did notice "greyish/white fibrous clumps scattered throughout the area" (see DOHS report in Appendix D). Three samples of this material were taken, one of which was split with LRTC. Elevated concentrations of heavy metals and asbestos were found (see sample results in Appendix D).

LRTC's alleged removal of soil, asphalt, and concrete from the United Heckathorn site to the Parr Canal site was apparently done before LRTC became aware of the contamination problems. After this alleged contaminant disposal in 1982, soil

TABLE 1

SUMMARY OF HLA PARR CANAL SAMPLE RESULTS

April-May, 1984

- ten test borings (B1-B10) on east side.
  - \*\*DDT concentrations (summation DDD, DDE, DDT) ranging from none detected (detection limit =.1 ppm) to 155.1 ppm.
- excavating four test pits (P1-P4) on east side.
  - \*\*DDT concentrations (summation) ranging from .15 ppm to 133 ppm.
  - \*\*PCB concentrations ranging from none detected (detection limit 1 ppm) to 70 ppm.

February, 1985

- ten test borings (A-J) four on east side, six on west side.
  - \*\*DDT concentrations (summation) ranging from none detected (detection limit .1 ppm) to 399 ppm.
  - \*\*Lead concentrations ranging from 11 ppm to 1,900 ppm.
- install and sample four monitor wells (A-D) on east side and sample standing water from borings G, H, I, and J on the west side.
  - \*\*No priority pollutants found.
  - \*\*Range of concentrations of metals found as follows (in mg/L):

Arsenic	.005 to .01
Barium	.12 to .35
Chromium	.014 to .019
Cobalt	.22
Copper	.002 to .014
Molybdenum	.09 to .16
Nickel	.03 to .06
Selenium	.006 to .007
Thallium	.2
Zinc	.016 to .048

TABLE 1.0 (continued)

March, 1985

-four borings in Canal sediments

\*\*Range of results in mg/L:

Arsenic	2.6 to 7.3
Barium	40 to 120
Chromium	41 to 53
Copper	30 to 60
Lead	80 to 230
Nickel	20 to 40
Vanadium	25 to 45
Zinc	50 to 190
DDT	5
DDD	2 to 9

June, 1985

-Bioassay by Aqua Terra (from wells A and B)

-toxicological research

-Waste Extraction Test (WET) for soluble lead and soluble DDT (from four soil samples; E, I, G, & J).

\*\*WET soluble lead results 27 and 42 mg/L

\*\*WET soluble DDT = none detected

-Parr Canal water analysis

\*\*Zinc and compounds detected at .14 mg/L

at Parr Canal was subsequently tested for DDT and concentrations ranging from 2 to 250 ppm were found (Ref. 15). It is unknown who took these samples and from where on the site they were taken.

On August 31, 1983, Harding-Lawson Associates (HLA), retained by LRTC to characterize the contamination at the Parr Canal site, submitted a plan to relocate and cover contaminated soils at the site. After analyzing, characterizing, relocating, and covering the soils, LRTC finally gained approval from the DOHS to remove the soils to a Class I disposal facility. A total of 3,362 tons of soil were removed to the I.T. Benicia Class I dump (manifests are available in the CERCLIS file). Additionally, 300 cubic yards of soil had apparently been taken to the Casmalia Class I dump prior to the relocating and covering of the 3,362 tons of soil. Any material with levels of DDT greater than 10 ppm or lead over 50 ppm was reportedly considered contaminated and was taken to the Class I dumps (Ref. 15).

DOHS samples taken January 18, 1984 at the Parr Canal site were found to contain approximately 45% asbestos. Two other soil samples taken on January 24, 1984 revealed DDT concentrations (summation of DDD, DDE, and DDT) of 34.8 ppm and 2.4 ppm, respectively.

HLA took more samples from the Parr Canal site on April 27 and May 11, 1984. These samples were taken both in areas where LRTC had placed soil (which had since been removed to the Class I dumps) and in areas that LRTC had allegedly not disturbed. Elevated levels of DDT and PCBs were found that apparently did not correlate with the known contaminated levels of material that LRTC had relocated from the United Heckathorn site. HLA concluded that the contamination was present prior to LRTC's moving the soils and concrete from the United Heckathorn site.

A summary of HLA's investigation, including contaminant concentration ranges, is presented in Table 1.

## 2.4 Permits

LRTC has a permit from the United States Army Corps of Engineers enabling the firm to dredge in the Lauritzen Canal and Santa Fe Channel. It is a 10-year permit (No. 14475E53, modified by 14475E43A) which expires on October 19, 1992. No record could be found of the Parr Canal ever having been dredged. However, there has been one modification of this permit with regard to the Parr Canal. LRTC applied to the Corps of Engineers to put shoring and riprap along the Canal edge. The Corps of Engineers approved this modification.

A conditional-use permit for the use of the land was granted to the previous owner (Parr Richmond Terminal Corp.) in 1965 by the City of Richmond.



## 2.5 Remedial Action

The Parr Canal site has undergone considerable remedial activity. Three hundred cubic yards of contaminated soil were removed to the Casmalia Class I dump and 3,362 tons of contaminated soil were disposed of at the I.T. Benicia Class I dump in September, 1984. The entire site was then prepared for final capping by removing existing vegetation, grading, and compacting surface soils. A permeable synthetic geotextile membrane was placed directly on the surface and covered with 12 inches of crushed gravel. The final report on the Parr Canal site has not been submitted to-date (9/9/86).

LRTC plans to construct a building and possibly rail lines on-site, operations that LRTC maintains will require no soil removal. LRTC has a Personnel Safety Plan developed by George Ceasar, CIH, of EAL Corporation, to protect employees who could be exposed to contaminated soils during routine maintenance and soil excavations.

The embankment areas along the side of the Canal will be protected from erosion by the placement of riprap. The cover system will be inspected on a monthly basis. The four existing groundwater monitor wells on the east side of the site, and four new wells to be constructed on the west side of the site will be monitored semi-annually for the first three years and then, depending on the results of these samplings, annually for the following two years. If monitoring continues to show no contamination at the end of five years, monitoring will be discontinued.

No remedial activity has been proposed for the Canal sediments. The RWQCB has recently stated that remedial measures on the Parr Canal will only be undertaken as part of the United Heckathorn/Lauritzen Canal remedial activities. This is due to the fact that the concentrations of DDT in the Parr Canal sediments are low compared to those in the Lauritzen Canal and therefore it would not be feasible to remediate these canal sediments alone. The heavy metals in the Parr Canal sediments are not of concern to the RWQCB (Ref. 1).

### 3 ENVIRONMENTAL SETTING

#### 3.1 Surrounding Area

The industrial area found along Richmond inner harbor surrounds this site on the south, west and east. The residential area of Richmond begins about three or four blocks north of the site. The population of Richmond is approximately 78,606.

San Francisco Bay extends into the site as the Parr Canal, which extends north from the Harbor Channel. According to Mike Rugg, Department of Fish and Game, there are no known environmental receptors (e.g. wetlands, critical habitats, endangered species, nature reserves, etc.) near the Parr Canal site.

The one-year, 24-hour rainfall for the Richmond area is approximately three inches. Net precipitation from November to April is 6.85 inches.

#### 3.2 Geology

Thick deposits of Bay mud underlie the site, and between three and 11 feet of fill sit on top of the Bay mud. This fill is heterogenous and was probably imported from the hills to the west. The permeability of similar fill material from the nearby United Heckathorn site (approximately 1/4 mile west) was found to be 0.0001 centimeters per second (cm/sec). The permeability of the Bay mud at the Heckathorn site was found to be approximately .000007 cm/sec (Ref. 15). Under the Bay mud there appears to be between 300 and 500 feet of alluvial deposits (Ref. 16).

#### 3.3 Hydrology

##### 3.3.1 Surface Water

The San Francisco Bay extends up to this site as the Harbor Channel from which the Parr Canal, Santa Fe Channel, and the Lauritzen Canal are extensions. All surface runoff from the site flows directly into the Parr Canal.

##### 3.3.2 Groundwater

According to well logs provided in HLA's report, the site is overlain with artificial fills varying in depth between three and 11 feet. Groundwater is found in this fill in some, but not all, on-site borings. The presence of water in the fill appears to be attributable to Bay water intrusion. The Bay mud underlying this fill is saturated with water (Ref. 15).

Contaminant migration to aquifers below the Bay mud is assumed to be unlikely because of the very low permeability of Bay mud. According to available sources, no groundwater within three miles of the site is used for domestic consumption or

irrigation. There are between 20 and 30 wells within three miles of the site, which the Department of Water Resources has recorded as cathodic protection wells, rather than production wells (17). Available records at the Contra Costa County Environmental Health Department do not show any private water systems dependent on groundwater in the Richmond area.

#### 4 SUMMARY OF FIT INVESTIGATIVE EFFORTS

On August 14, 1986, FIT investigators Doug Russell and Mike Grant inspected the Levin-Richmond Terminal Corporation facilities. The site inspection began with a meeting, followed by a tour of the site and of areas with DDT contamination. Present at the meeting were:

- Thomas Peterson, Vice President and General Manager, LRTC
- Mike McCoy, Marketing Representative, LRTC
- Jim Cannon, Design Engineer, LRTC
- Stephen Peck, Attorney for LRTC
- Keith Howard, Attorney for LRTC
- William Frizzell, Associate Engineer, HLA
- Douglas Russell, Ecology and Environment, Inc.
- Mike Grant, Ecology and Environment, Inc.

Following the meeting, William Frizzell escorted Mike Grant and Doug Russell to the Parr Canal area. The site was fenced and locked. There were signs posted that read, in both english and spanish: "Caution, Hazardous Waste Storage Area; Unauthorized Persons Keep Out." Mr. Frizzell unlocked the gate and we began the tour. The site had little topographic relief and was completely covered with crushed gravel. We observed the synthetic geotextile membrane at the Canal edge, where the placement of the riprap had not yet been completed. Pictures of the site were taken and are presented in Appendix B.

## 5 HRS FACTORS

### o Observed Release:

Levels of arsenic, barium, chromium, cobalt, copper, molybdenum, nickel, selenium, thallium, and zinc were found in groundwater samples on-site. All concentrations were below the STLCs and Drinking Water Standards (MCLs).

Analysis of Parr Canal water revealed zinc compound concentrations of .14 mg/l.

Though they do not constitute actual observed releases, the following heavy metals and DDT compounds were found in the canal sediments: arsenic, barium, chromium, copper, lead, nickel, vanadium, zinc, DDT, and DDD.

See Table 1 for levels of contaminants found in all sampling done by HLA.

### o Direct Contact/Fire and Explosion:

There are no known cases of direct contact. Prior to the remedial work done on-site, the potential for direct contact with asbestos, PCBs, DDT, and heavy metals was high. Though the entire landward side of the site is fenced and locked, both employees with access and people entering the lot from the canal side may have been exposed to these contaminants. Currently, the likely exposure routes to the public would be consumption of contaminated organisms (mollusks, fish, etc.) from the adjacent Bay waters and people coming into contact with canal sediments.

### o Waste Type:

The following compounds have been identified in samples taken from the site: DDT, DDD, DDE, heavy metals, asbestos, and PCBs.

### o Waste Quantity:

There is no documentation available on the quantities of the contaminants found on-site.

### o Groundwater:

According to the best available sources, the surrounding area is underlain by thick deposits of Bay mud which would inhibit contaminant migration to aquifers below this mud layer. In addition, the FIT investigation did not locate any uses of the groundwater for domestic or irrigation purposes within three miles of the site.

### o Surface Water:

Runoff from the entire site drains directly into the Parr Canal and Harbor Channel. The Harbor Channel is an extension of the San Francisco Bay. The Parr Canal, the Harbor Channel, and the San Francisco Bay are all used for fishing, swimming, boating, aesthetic enjoyment, etc.

o Other Factors:

The contaminants found in the Parr Canal sediments are potentially of concern. This site, in all probability, will not score high enough for NPL inclusion, yet there still is a concern that the sediments pose a threat to human health and lower organisms. High levels of heavy metals, as well as DDT and DDD, have been found in the canal sediments. The pathway leading to their deposit has not been identified. These contaminants may have come from on-site areas that have not been well characterized, either through storm drain runoff via the outfall at the north end of the canal, or by mechanical action of tides and currents.



## 6 OTHER AGENCY INVOLVEMENT

The following agencies have been involved with the Parr Canal site:

- o The RWQCB has been active in the Parr Canal contamination problems. Its concerns have been mainly with groundwater, surface water, and canal sediments. It drafted two Cleanup and Abatement Orders (Nos. 84-001 and 84-008) neither of which LRTC responded to sufficiently. Robin Breuer is currently the project leader at the RWQCB.

- o The DOHS has also been active at the Parr Canal site. Its concerns are mainly with the contaminated soil. It drafted a Survey and Compliance Order which is now outdated. Claudia Willen is currently the project leader for the DOHS.

- o The Department of Fish and Game has also been involved in the role of a reviewer. The Parr Canal waters and the wildlife it contains have been the concerns of the DFG. Mike Rugg has been the project leader.

- o The Contra Costa County Environmental Health Department is also involved with this site, primarily to review and keep up-to-date on all activities. Dan Bergman and Ken Axe are project leaders.

## 7 CONCLUSIONS

The history of this site is not well documented. There have been several landowners and businesses that could have contributed to the contamination found on-site. Sampling has shown evidence of heavy metals, asbestos, PCBs, and DDT. There are two areas of concern at the Parr Canal site, the soils and the canal sediments.

### SOILS:

Remedial activity, consisting of soil removal, has concentrated on protecting human health and the environment from the DDT on the Parr Canal site. These remedial measures did not address the asbestos, PCBs, and heavy metal contamination on the site. However, the asbestos is now immobilized due to the site having been covered with the geotextile membrane and crushed rock. (The heavy metals found in the soils and groundwater are the likely result of ship building and scrap-metal operations that have occurred in the area in the past.) It is presently unknown if the soluble lead extracted from the soil has been remediated. It is also unknown if the PCB contaminated soil has been removed or remediated. The permeable membrane covering the site will allow vertical migration of precipitation into the underlying fill; this creates the potential for contaminants in the fill to leach out laterally along the Bay mud into the canal.

### CANAL and SEDIMENTS:

The canal water was found to contain 0.14 mg/l of zinc and related compounds. The effect of this level of zinc on the quality of the Bay waters, human health, or the environment is unknown. The canal sediments contain levels of arsenic, barium, chromium, copper, lead, nickel, vanadium, DDT, and DDD that are all above the STLCs set in the California Administrative Code, Title 22. The bioavailability and effect of the heavy metals on the quality of the Bay waters, human health, or the environment is presently unknown. There is significant controversy as to whether DDT is bioavailable in its present state in the sediments.

## 8 RECOMMENDATIONS

Due to the unknown occupancy history of the site, and to the wide variety of contaminants found, FIT makes the following recommendations:

*not  
sequence, but  
it includes what is  
OK*

o A potential responsible party (PRP) search be conducted to help further characterize the possible extent and sources of existing contamination. This PRP search will be conducted as part of the FIT Contra Costa County investigation.

*monitor  
✓ RWQCB study*

o The potential human and environmental health effects from heavy-metal and DDT-contaminated canal sediments should be assessed. The RWQCB has recently proposed conducting a Clean-up and Abatement Study in the Richmond Harbor area. This study would be directed towards discovering which aquatic species are being contaminated and what the sources of the contamination are. The EPA and FIT should both be involved with this study at least in the role of review and assistance.

7 o The PCB-contaminated soil areas should be characterized and a determination should be made as to the potential effect on human health and on the environment. Sampling should be conducted to determine if precipitation and subsequent percolation and/or run-off could be contributing contaminants to the canal. FIT will prepare a sampling plan addressing this scope of work, if EPA deems this necessary.

✓ o The entire Richmond harbor (land and water) may have varying levels of heavy metal, PCB, and asbestos contamination, due to the history of ship building and scrap-metal operations in the area. The area should be assessed with the focus on the human health and environmental health effects that these contaminants may have. FIT will further characterize this area in the Contra Costa County investigation and will make an assessment on the effects to human health and environmental welfare that these contaminants may pose.

✓ Recommend remediation of Lumbis Canal site

9 REFERENCES

- 1 - Contact report between Doug Russell, FIT, and Robin Breuer, RWQCB, October 2, 1986.
- 2 - Letter from John L. Kallok, Montrose Chemical Corporation of California, to Beth Jines, DOHS. December 2, 1981.
- 3 - Moore, Clifford, Wolfe, Larson, & Trutner, Attorneys at Law, Attachment A, Request for file review to the Department of Fish and Game.
- 4 - Moore, Clifford, Wolfe, Larson, & Trutner, Attorneys at Law, Joint Pretrial Statement of All Parties, U.S. District Court for the Northern District, No. C 85 4776 SC, January 28, 1986.
- 5 - Department of Fish and Game, Inter-Departmental Communication to John Harrison, RWQCB, January 23, 1952.
- 6 - Department of Fish and Game, Pollution Complaint from Robert Jones, DFG to Ellis Berry, DFG, June 3, 1960.
- 7 - Department of Fish and Game, Inter-Departmental Communication, Fred Kemp to H. E. Pintler, DFG, August 11, 1960.
- 8 - Department of Fish and Game Memo from Fred Kemp, DFG to Donald Lollock, DFG, January 18, 1965.
- 9 - Abandoned Site Project Site Inspection, August 13, 1980.
- 10 - EAL Corporation Analysis Report for Harding-Lawson Associates, December 7, 1981.
- 11 - Department of Health Services, Hazardous Waste Site Surveillance and Compliance Report, August 31, 1982.
- 12 - Department of Health Services, Memorandum from Richard Jackson to Charles White, October 17, 1983.
- 13 - Department of the Army, San Francisco District, Corps of Engineers, Notice of Authorization, November 12, 1982 and Permit, January 26, 1982.
- 14 - Regional Water Quality Control Board, Checking Program Report, June 15, 1960.
- 15 - Harding-Lawson Associates, Site Characterization and Remedial Action Plan, Parr Canal Site, June 27, 1985.

- 16 - California Division of Mines and Geology, Preliminary Report 19, Geological and Geophysical Investigations for Tri-Cities Seismic Safety and Environmental Resources Study, 1973.
- 17 - Contact Log Between Doug Russell, FIT and Betty Swatsenburg, DWR, September 12, 1986.

## APPENDIX A





POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 1 - SITE LOCATION AND INSPECTION INFORMATION

I. IDENTIFICATION  
01 STATE 02 SITE NUMBER

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site)

LRTC / Parr Canal Site

02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER

8th and Wright Ave.

03 CITY

Richmond

04 STATE

05 ZIP CODE

06 COUNTY

CA

94804

Contra Costa

07 COUNTY CODE

08 CONG DIST

09 COORDINATES  
LATITUDE

LONGITUDE

10 TYPE OF OWNERSHIP (Check one)

☒ A. PRIVATE ☐ B. FEDERAL ☐ C. STATE ☐ D. COUNTY ☐ E. MUNICIPAL  
☐ F. OTHER ☐ G. UNKNOWN

III. INSPECTION INFORMATION

01 DATE OF INSPECTION

8/14/86  
MONTH DAY YEAR

02 SITE STATUS

☒ ACTIVE  
☐ INACTIVE

03 YEARS OF OPERATION

1920s Present  
BEGINNING YEAR ENDING YEAR

UNKNOWN

04 AGENCY PERFORMING INSPECTION (Check all that apply)

☐ A. EPA ☒ B. EPA CONTRACTOR Ecology & Env. Inc. (Name of firm)  
☐ C. MUNICIPAL ☐ D. MUNICIPAL CONTRACTOR (Name of firm)  
☐ E. STATE ☐ F. STATE CONTRACTOR (Name of firm) ☐ G. OTHER (Specify)

05 CHIEF INSPECTOR

Douglas Russell

06 TITLE

Env. Scientist

07 ORGANIZATION

E+E

08 TELEPHONE NO.

(415) 777-2811

09 OTHER INSPECTORS

Mike Grant

10 TITLE

Env. Scientist

11 ORGANIZATION

E+E

12 TELEPHONE NO.

(415) 777-2811

13 SITE REPRESENTATIVES INTERVIEWED

Tom Peterson

14 TITLE

VP

15 ADDRESS

402 Wright

16 TELEPHONE NO.

(415) 232-4422

Mike McCoy

Marketing Rep.

402 Wright

(415) 232-4422

17 ACCESS GAINED BY  
(Check one)

☐ PERMISSION  
☐ WARRANT

18 TIME OF INSPECTION

19 WEATHER CONDITIONS

IV. INFORMATION AVAILABLE FROM

01 CONTACT

02 OF (Agency/Organization)

03 TELEPHONE NO.

( )

04 PERSON RESPONSIBLE FOR SITE INSPECTION FORM


05 AGENCY

06 ORGANIZATION

07 TELEPHONE NO.

08 DATE

MONTH DAY YEAR

[illegible]



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. HAZARDOUS CONDITIONS AND INCIDENTS

01 ☒ A. GROUNDWATER CONTAMINATION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

heavy metals, potential for PCB

01 ☒ B. SURFACE WATER CONTAMINATION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

Potential for DDT and PCB, and heavy metal  
to leach into canal.

01 ☐ C. CONTAMINATION OF AIR

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

01 ☐ D. FIRE/EXPLOSIVE CONDITIONS

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

01 ☒ E. DIRECT CONTACT

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

Contaminated aquatic species

01 ☒ F. CONTAMINATION OF SOIL

02 ☒ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 AREA POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

Asbestos, PCB, Heavy Metal, DDT

01 ☐ G. DRINKING WATER CONTAMINATION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

01 ☐ H. WORKER EXPOSURE/INJURY

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 WORKERS POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION

01 ☐ I. POPULATION EXPOSURE/INJURY

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

04 NARRATIVE DESCRIPTION



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☐ J. DAMAGE TO FLORA  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

01 ☐ K. DAMAGE TO FAUNA  
04 NARRATIVE DESCRIPTION (include name(s) of species)

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

01 ☒ L. CONTAMINATION OF FOOD CHAIN  
04 NARRATIVE DESCRIPTION

02 ☒ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

Fish + Mollusk samples show DDT in flesh

01 ☐ M. UNSTABLE CONTAINMENT OF WASTES  
(Spills/Runoff/Standing liquids, Leaking drums)  
03 POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

04 NARRATIVE DESCRIPTION

01 ☒ N. DAMAGE TO OFFSITE PROPERTY  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

SF Bay sediment w/ DDT

01 ☐ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

01 ☒ P. ILLEGAL/UNAUTHORIZED DUMPING  
04 NARRATIVE DESCRIPTION

02 ☒ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL

☐ ALLEGED

Haz. DDT wastes brought to site in past.  
(It was apparently unknown that it contained DDT)

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS

III. TOTAL POPULATION POTENTIALLY AFFECTED: \_\_\_\_\_

IV. COMMENTS

V. SOURCES OF INFORMATION (Cite specific references, e. g., state files, sample analysis, reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION  
PART 4 - PERMIT AND DESCRIPTIVE INFORMATION

I. IDENTIFICATION  
01 STATE 02 SITE NUMBER

II. PERMIT INFORMATION

01 TYPE OF PERMIT ISSUED (Check all that apply)	02 PERMIT NUMBER	03 DATE ISSUED	04 EXPIRATION DATE	05 COMMENTS
<input type="checkbox"/> A. NPDES				
<input type="checkbox"/> B. UIC				
<input type="checkbox"/> C. AIR				
<input type="checkbox"/> D. RCRA				
<input type="checkbox"/> E. RCRA INTERIM STATUS				
<input type="checkbox"/> F. SPCC PLAN				
<input type="checkbox"/> G. STATE (Specify)				
<input checked="" type="checkbox"/> H. LOCAL (Specify) <u>Land-use</u>				
<input type="checkbox"/> I. OTHER (Specify)				
<input type="checkbox"/> J. NONE				

III. SITE DESCRIPTION

01 STORAGE/DISPOSAL (Check all that apply)	02 AMOUNT	03 UNIT OF MEASURE	04 TREATMENT (Check all that apply)	05 OTHER
<input type="checkbox"/> A. SURFACE IMPOUNDMENT			<input type="checkbox"/> A. INCENERATION	<input type="checkbox"/> A. BUILDINGS ON SITE
<input type="checkbox"/> B. PILES			<input type="checkbox"/> B. UNDERGROUND INJECTION	
<input type="checkbox"/> C. DRUMS, ABOVE GROUND			<input type="checkbox"/> C. CHEMICAL/PHYSICAL	
<input type="checkbox"/> D. TANK, ABOVE GROUND			<input type="checkbox"/> D. BIOLOGICAL	
<input type="checkbox"/> E. TANK, BELOW GROUND			<input type="checkbox"/> E. WASTE OIL PROCESSING	
<input type="checkbox"/> F. LANDFILL			<input type="checkbox"/> F. SOLVENT RECOVERY	06 AREA OF SITE
<input type="checkbox"/> G. LANDFARM			<input type="checkbox"/> G. OTHER RECYCLING/RECOVERY	<u>12</u> (Acres)
<input type="checkbox"/> H. OPEN DUMP			<input type="checkbox"/> H. OTHER (Specify)	
<input type="checkbox"/> I. OTHER (Specify)				

07 COMMENTS

IV. CONTAINMENT

01 CONTAINMENT OF WASTES (Check one)

☒ A. ADEQUATE, SECURE    ☒ B. MODERATE    ☐ C. INADEQUATE, POOR    ☐ D. INSECURE, UNSOUND, DANGEROUS

02 DESCRIPTION OF DRUMS, DIKING, LINERS, BARRIERS, ETC.

V. ACCESSIBILITY

01 WASTE EASILY ACCESSIBLE: ☐ YES ☐ NO

02 COMMENTS

VI. SOURCES OF INFORMATION (Cite specific references, e.g. state files, sample analysis, reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. DRINKING WATER SUPPLY

01 TYPE OF DRINKING SUPPLY  
(Check as applicable)

SURFACE WELL  
COMMUNITY A. ☐ B. ☐  
NON-COMMUNITY C. ☐ D. ☐

02 STATUS

ENDANGERED AFFECTED MONITORED  
A. ☐ B. ☐ C. ☐  
D. ☐ E. ☐ F. ☐

03 DISTANCE TO SITE

A. \_\_\_\_\_ (mi)  
B. \_\_\_\_\_ (mi)

III. GROUNDWATER

01 GROUNDWATER USE IN VICINITY (Check one)

☐ A. ONLY SOURCE FOR DRINKING

☐ B. DRINKING  
(Other sources available)  
COMMERCIAL, INDUSTRIAL, IRRIGATION  
(No other water sources available)

☐ C. COMMERCIAL, INDUSTRIAL, IRRIGATION  
(Limited other sources available)

☒ D. NOT USED, UNUSEABLE

02 POPULATION SERVED BY GROUND WATER \_\_\_\_\_

03 DISTANCE TO NEAREST DRINKING WATER WELL \_\_\_\_\_ (mi)

04 DEPTH TO GROUNDWATER

\_\_\_\_\_ (ft)

05 DIRECTION OF GROUNDWATER FLOW

\_\_\_\_\_

06 DEPTH TO AQUIFER  
OF CONCERN

\_\_\_\_\_ (ft)

07 POTENTIAL YIELD  
OF AQUIFER

\_\_\_\_\_ (gpd)

08 SOLE SOURCE AQUIFER

☐ YES ☐ NO

09 DESCRIPTION OF WELLS (including usage, depth, and location relative to population and buildings)

all wells are for cathodic protection

10 RECHARGE AREA

☐ YES  
☐ NO

COMMENTS

11 DISCHARGE AREA

☐ YES  
☐ NO

COMMENTS

IV. SURFACE WATER

01 SURFACE WATER USE (Check one)

☒ A. RESERVOIR, RECREATION  
DRINKING WATER SOURCE

☐ B. IRRIGATION, ECONOMICALLY  
IMPORTANT RESOURCES

☐ C. COMMERCIAL, INDUSTRIAL

☐ D. NOT CURRENTLY USED

02 AFFECTED/POTENTIALLY AFFECTED BODIES OF WATER

NAME:

Parr Canal, Harbor Channel, San Fran. Bay

AFFECTED

DISTANCE TO SITE

4.1 (mi)  
\_\_\_\_\_  
\_\_\_\_\_  
(mi)  
(mi)

V. DEMOGRAPHIC AND PROPERTY INFORMATION

01 TOTAL POPULATION WITHIN

ONE (1) MILE OF SITE

A. \_\_\_\_\_  
NO. OF PERSONS

TWO (2) MILES OF SITE

B. \_\_\_\_\_  
NO. OF PERSONS

THREE (3) MILES OF SITE

C. 78,000  
NO. OF PERSONS

02 DISTANCE TO NEAREST POPULATION

4.1 (mi)

03 NUMBER OF BUILDINGS WITHIN TWO (2) MILES OF SITE

lots

04 DISTANCE TO NEAREST OFF-SITE BUILDING

4.1 (mi)

05 POPULATION WITHIN VICINITY OF SITE (Provide narrative description of nature of population within vicinity of site, e.g., rural, village, densely populated urban area)

Richmond population = 78,000





POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

VI. ENVIRONMENTAL INFORMATION

01 PERMEABILITY OF UNSATURATED ZONE (Check one)

☒ A.  $10^{-8} - 10^{-6}$  cm/sec ☒ B.  $10^{-4} - 10^{-6}$  cm/sec ☐ C.  $10^{-4} - 10^{-3}$  cm/sec ☐ D. GREATER THAN  $10^{-3}$  cm/sec

02 PERMEABILITY OF BEDROCK (Check one)

☐ A. IMPERMEABLE (Less than  $10^{-8}$  cm/sec) ☐ B. RELATIVELY IMPERMEABLE ( $10^{-4} - 10^{-6}$  cm/sec) ☐ C. RELATIVELY PERMEABLE ( $10^{-2} - 10^{-4}$  cm/sec) ☐ D. VERY PERMEABLE (Greater than  $10^{-2}$  cm/sec)

03 DEPTH TO BEDROCK

\_\_\_\_ (ft)

04 DEPTH OF CONTAMINATED SOIL ZONE

2 (ft)

05 SOIL pH

06 NET PRECIPITATION

6.85 (in)

07 ONE YEAR 24 HOUR RAINFALL

3 (in)

08 SLOPE  
SITE SLOPE

DIRECTION OF SITE SLOPE TERRAIN AVERAGE SLOPE

09 FLOOD POTENTIAL

SITE IS IN \_\_\_\_\_ YEAR FLOODPLAIN

10

☐ SITE IS ON BARRIER ISLAND, COASTAL HIGH HAZARD AREA, RIVERINE FLOODWAY

11 DISTANCE TO WETLANDS (5 acre minimum)

ESTUARINE

OTHER

A. \_\_\_\_\_ (mi)

B. \_\_\_\_\_ (mi)

12 DISTANCE TO CRITICAL HABITAT (of endangered species)

\_\_\_\_\_ (mi)

ENDANGERED SPECIES: \_\_\_\_\_

13 LAND USE IN VICINITY

DISTANCE TO:

COMMERCIAL/INDUSTRIAL

RESIDENTIAL AREAS; NATIONAL/STATE PARKS,  
FORESTS, OR WILDLIFE RESERVES

AGRICULTURAL LANDS  
PRIME AG LAND AG LAND

A. 0.1 (mi)

B. \_\_\_\_\_ (mi)

C. \_\_\_\_\_ (mi)

D. \_\_\_\_\_ (mi)

14 DESCRIPTION OF SITE IN RELATION TO SURROUNDING TOPOGRAPHY

VII. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 6 - SAMPLE AND FIELD INFORMATION

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. SAMPLES TAKEN

SAMPLE TYPE	01 NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO	03 ESTIMATED DATE RESULTS AVAILABLE
GROUNDWATER	X		
SURFACE WATER	X		
WASTE			
AIR			
RUNOFF			
SPILL			
SOIL	X		
VEGETATION			
<del>PLANT</del> Fish	X		

III. FIELD MEASUREMENTS TAKEN

01 TYPE	02 COMMENTS

IV. PHOTOGRAPHS AND MAPS

01 TYPE <input type="checkbox"/> GROUND <input checked="" type="checkbox"/> AERIAL	02 IN CUSTODY OF <u>LRTC</u> <small>(Name of organization or individual)</small>
03 MAPS <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	04 LOCATION OF MAPS <u>In Report</u>

V. OTHER FIELD DATA COLLECTED (Provide narrative description)

VI. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 7 - OWNER INFORMATION

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. CURRENT OWNER(S)

01 NAME <b>Levin Metals RTC</b>				02 D+B NUMBER				08 NAME <b>Levin Metals</b>				09 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.) <b>402 Wright</b>				04 SIC CODE				10 STREET ADDRESS (P.O. Box, RFD #, etc.) <b>1300 Canal</b>				11 SIC CODE											
05 CITY <b>Richmond</b>				06 STATE <b>CA</b>				07 ZIP CODE <b>94804</b>				12 CITY <b>Richmond</b>				13 STATE <b>CA</b>				14 ZIP CODE <b>94804</b>			
01 NAME				02 D+B NUMBER				08 NAME				09 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE				10 STREET ADDRESS (P.O. Box, RFD #, etc.)				11 SIC CODE											
05 CITY				06 STATE				07 ZIP CODE				12 CITY				13 STATE				14 ZIP CODE			
01 NAME				02 D+B NUMBER				08 NAME				09 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE				10 STREET ADDRESS (P.O. Box, RFD #, etc.)				11 SIC CODE											
05 CITY				06 STATE				07 ZIP CODE				12 CITY				13 STATE				14 ZIP CODE			
01 NAME				02 D+B NUMBER				08 NAME				09 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE				10 STREET ADDRESS (P.O. Box, RFD #, etc.)				11 SIC CODE											
05 CITY				06 STATE				07 ZIP CODE				12 CITY				13 STATE				14 ZIP CODE			

III. PREVIOUS OWNER(S) (List most recent first)

01 NAME <b>Parr Rich. Term. Corp.</b>				02 D+B NUMBER				01 NAME				02 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.) <b>402 Wright Ave</b>				04 SIC CODE				03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE											
05 CITY <b>Richmond</b>				06 STATE <b>CA</b>				07 ZIP CODE <b>94804</b>				05 CITY				06 STATE				07 ZIP CODE			
01 NAME				02 D+B NUMBER				01 NAME				02 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE				03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE											
05 CITY				06 STATE				07 ZIP CODE				05 CITY				06 STATE				07 ZIP CODE			
01 NAME				02 D+B NUMBER				01 NAME				02 D+B NUMBER											
03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE				03 STREET ADDRESS (P.O. Box, RFD #, etc.)				04 SIC CODE											
05 CITY				06 STATE				07 ZIP CODE				05 CITY				06 STATE				07 ZIP CODE			

V. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 8 - OPERATOR INFORMATION

I. IDENTIFICATION  
01 STATE 02 SITE NUMBER

II. CURRENT OPERATOR (Provide if different from owner)

OPERATOR'S PARENT COMPANY (if applicable)

01 NAME LRTC			02 D+B NUMBER			10 NAME Levin Metals			11 D+B NUMBER								
03 STREET ADDRESS (P.O. Box, RFD #, etc.) 402 Wright Ave.			04 SIC CODE			12 STREET ADDRESS (P.O. Box, RFD #, etc.) 1310 Canal			13 SIC CODE								
05 CITY Richmond			06 STATE CA			07 ZIP CODE 94804			14 CITY Richmond			15 STATE CA			16 ZIP CODE 94804		
08 YEARS OF OPERATION 5			09 NAME OF OWNER Levin Rich. Term. Corp.														

III. PREVIOUS OPERATOR(S) (List most recent first, provide only if different from owner)

PREVIOUS OPERATORS' PARENT COMPANIES (if applicable)

01 NAME			02 D+B NUMBER			10 NAME			11 D+B NUMBER								
03 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE			12 STREET ADDRESS (P.O. Box, RFD #, etc.)			13 SIC CODE								
05 CITY			06 STATE			07 ZIP CODE			14 CITY			15 STATE			16 ZIP CODE		
08 YEARS OF OPERATION			09 NAME OF OWNER DURING THIS PERIOD														
01 NAME			02 D+B NUMBER			10 NAME			11 D+B NUMBER								
03 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE			12 STREET ADDRESS (P.O. Box, RFD #, etc.)			13 SIC CODE								
05 CITY			06 STATE			07 ZIP CODE			14 CITY			15 STATE			16 ZIP CODE		
08 YEARS OF OPERATION			09 NAME OF OWNER DURING THIS PERIOD														
01 NAME			02 D+B NUMBER			10 NAME			11 D+B NUMBER								
03 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE			12 STREET ADDRESS (P.O. Box, RFD #, etc.)			13 SIC CODE								
05 CITY			06 STATE			07 ZIP CODE			14 CITY			15 STATE			16 ZIP CODE		
08 YEARS OF OPERATION			09 NAME OF OWNER DURING THIS PERIOD														

IV. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 9 - GENERATOR/TRANSPORTER INFORMATION

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. ON-SITE GENERATOR

01 NAME	02 D+B NUMBER	
03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE	
05 CITY	06 STATE	07 ZIP CODE

III. OFF-SITE GENERATOR(S)

01 NAME	02 D+B NUMBER	01 NAME	02 D+B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
01 NAME	02 D+B NUMBER	01 NAME	02 D+B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE

IV. TRANSPORTER(S)

01 NAME	02 D+B NUMBER	01 NAME	02 D+B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
01 NAME	02 D+B NUMBER	01 NAME	02 D+B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE	03 STREET ADDRESS (P.O. Box, RFD #, etc.)	04 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE

V. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)

--



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 10 - PAST RESPONSE ACTIVITIES

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

B. PAST RESPONSE ACTIVITIES

01 ☐ A. WATER SUPPLY CLOSED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ B. TEMPORARY WATER SUPPLY PROVIDED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ C. PERMANENT WATER SUPPLY PROVIDED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☒ D. SPILLED MATERIAL REMOVED  
04 DESCRIPTION

02 DATE

03 AGENCY

~~500 yds of highly contaminated soil and sludge~~

01 ☒ E. CONTAMINATED SOIL REMOVED  
04 DESCRIPTION

02 DATE

03 AGENCY

3662 yards of contaminated soil

01 ☐ F. WASTE REPACKAGED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☒ G. WASTE DISPOSED ELSEWHERE  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☒ H. ON SITE BURIAL  
04 DESCRIPTION

02 DATE

03 AGENCY

DDT contaminated soil left on site

01 ☐ I. IN SITU CHEMICAL TREATMENT  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ J. IN SITU BIOLOGICAL TREATMENT  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ K. IN SITU PHYSICAL TREATMENT  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☒ L. ENCAPSULATION  
04 DESCRIPTION

02 DATE

03 AGENCY

geotextile permeable membrane

01 ☐ M. EMERGENCY WASTE TREATMENT  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ N. CUTOFF WALLS  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ O. EMERGENCY DIKING/SURFACE WATER DIVERSION  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ P. CUTOFF TRENCHES/SUMP  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ Q. SUBSURFACE CUTOFF WALL  
04 DESCRIPTION

02 DATE

03 AGENCY



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 10 - PAST RESPONSE ACTIVITIES

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. PAST RESPONSE ACTIVITIES (Continued)

01 ☐ R. BARRIER WALLS CONSTRUCTED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ S. CAPPING/COVERING  
04 DESCRIPTION

02 DATE

03 AGENCY

geotextile permeable membrane over DDT soils

01 ☐ T. BULK TANKAGE REPAIRED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ U. GROUT CURTAIN CONSTRUCTED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ V. BOTTOM SEALED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ W. GAS CONTROL  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ X. FIRE CONTROL  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ Y. LEACHATE TREATMENT  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ Z. AREA EVACUATED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☒ 1. ACCESS TO SITE RESTRICTED  
04 DESCRIPTION

02 DATE

03 AGENCY

Site is fenced and locked from railroad sides

01 ☐ 2. POPULATION RELOCATED  
04 DESCRIPTION

02 DATE

03 AGENCY

01 ☐ 3. OTHER REMEDIAL ACTIVITIES  
04 DESCRIPTION

02 DATE

03 AGENCY

III. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)



POTENTIAL HAZARDOUS WASTE SITE  
SITE INSPECTION REPORT  
PART 11 - ENFORCEMENT INFORMATION

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. ENFORCEMENT INFORMATION

01 PAST REGULATORY/ENFORCEMENT ACTION ☒ YES ☐ NO

02 DESCRIPTION OF FEDERAL, STATE, LOCAL REGULATORY/ENFORCEMENT ACTION

III. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)



## APPENDIX B

PA/SI CONTACT LOG

Facility Name: Levin-Richmond Term. Corp.  
Facility ID: CAD 980673560

Name	Affiliation	Phone #	Date	Information
Robin Breuer	RWQCB	464-4223	7/10/86	I'll call before coming to review the files and folders.
Claudia Willen	DOHS	372-4416	7/10/86	There is an extensive file. Also, couple of lawsuit pending. I will call to set up a meeting to review the file.
Dan Bergman	Contra Costa County Env. Health	372-4416	7/10/86	He has a file and chronological update on the 16 State Superfund sites. Refer to Ken Axe.
Mike Rugg	Dept. Fish and Game	707-944-2011	7/10/86	Involvement as review. Have file on United Heckatorn. File copied.
	Dept. Fish and Game	707-944-2011	7/15/86	File copied.
	Contra Costa Env. Health	372-4416	7/15/86	File copied.

PRELIMINARY ASSESSMENT CONTACT LOG

Facility Name: Levin-Richmond Term. Corp.  
Facility ID: CAD 980673560

Name	Affiliation	Phone #	Date	Information
unknown	F.B.I.	553-7400	7/29/86	F.B.I. files are confidential to almost everyone. I should send a letter on EPA letter head with my requests to: Legal Section, F.B.I., 450 Golden Gate Avenue, S.F., CA 94102
Terry Rogers	U.S. Coast Guard	437-3087	7/29/86	No file information is likely before 1980. He will look into it and return my call.
unknown	U.S. Army Corps of engineers	974-0443	7/29/86	Try Regulatory People who keep records on permit activity for dredging. Also try-Trudy Reilly at 2 Main St., 9th Flr.
Terry Rogers	U.S. Coast Guard	437-3087	7/31/86	There have been no oil spill incidents in Lauritzen Canal since 1980. No records are kept before this. Oil spill report will be sent.
Rich Davidson	Richmond Public Works Dept.	620-6536	7/31/86	His dept. has nothing. I should try Building Dept and/or Planning Dept. (Nancy Kaufman or Tricia Murphy).

PRELIMINARY ASSESSMENT CONTACT LOG

Facility Name: Levin-Richmond Term. Corp.  
Facility ID: CAD 980673560

Name	Affiliation	Phone #	Date	Information
	Planning Dept.	620-6706	9/02/86	Population of Richmond 78,606. Bria Cook is census person and may have more info. on smaller areas.
?	LRTC	232-4422	9/02/86	Two or three drums of waste oil and solvents were found on-site and disposed of off-site. This oil was resultant from heavy equipment and wash parts oil draining
Dario LaVagie	Air Quality Control Board	771-6000	9/12/86	Prevailing wind is generally from the west or northwest. They have air monitoring stations in Richmond at 1065 - 7th and 1144 - 13th. They do not analyze for DDT, but might upon request.
Ken Axe	Contra Costa County Health Department	372-2521	9/12/86	No small water systems in West County. Possibly, families put wells in during drought and have since been abandoned.
Betty Swatsenbarg	DWR	916-322-7171	9/12/86	Richmond inner harbor has 20-30 well logs going three miles. They are cathodic protection wells.

CONTACT REPORT

AGENCY: Department of Fish and Game  
ADDRESS:  
PERSON  
CONTACTED: Mike Rugg  
PHONE NO.: 707-944-2011  
FROM: Doug Russell  
TO: File  
DATE: 9/2/86  
SUBJECT: Levin-Richmond Parr Canal  
CC:

The fish samples analysis revealed DDT concentrations in all fillets, below FDA action levels, whole body fish samples were the highest levels in the State. He is sending the results to me.

There are no wetlands, critical habitats, endangered species, or nature reserves near the Santa Fe Channel Area.

# CONTACT REPORT

AGENCY: LRTC  
ADDRESS: 402 Wright Avenue  
PERSON  
CONTACTED: Tom Peterson, Vice-President and General Manager  
PHONE NO.: 232-4422  
FROM: Doug Russell  
TO: File  
DATE: 9/18/86  
SUBJECT: Containers of PCB material and dredge info.  
CC:

The PCB drums contained, to the best of his recollection, "PCB transformers and possibly switch gear from old equipment (cranes, etc.) that were on-site".

Dredging has occurred twice since 1981, once along Berth A and once along Berth B and some of A. Mike McCoy will look into the dates and quantities and return my call. He also should have info. on who did the dredging and where it was taken.

# CONTACT REPORT

AGENCY: RWQCB  
ADDRESS: 1111 Jackson St., Oakland  
PERSON  
CONTACTED: Robin Breuer  
PHONE NO.: 464-4223  
FROM: Doug Russell  
TO: File  
DATE: 10/2/86  
SUBJECT: Parr Canal sediments, C & A Orders, Aqua Terra study.  
CC:

The Parr Canal sediments will not be addressed unless remediated at the time Lauritzen Canal sediments are remediated. PCB's in soil are DOHS concern. Heavy metals in sediments are not of concern. DDT in sediments are in low levels compared to Lauritzen Canal, and are not feasible to clean-up as a single project.

The Aqua Terra biological study is not being used as the basis for anything; it is bogus.

The two Clean-up and Abatement Orders were violated due to: reports not submitted on-time, site characterization was incomplete, and reports were insufficient.

## APPENDIX C



FIELD PHOTOGRAPHY LOG SHEET

DATE August 14, 1986

TIME 11 (A.M.) (P.M.)

DIRECTION: N NNE NE ENE

E ESE SE SSE

(S) SSW SW WSW

W WNW NW NNW

WEATHER Sunny, Warm

SITE Parr Canal

PHOTOGRAPHED BY:

Mike Grant

SAMPLE ID# (if applicable)



DESCRIPTION: Picture taken from entrance gate in northwest corner of lot. Time Oil tank farm on right.

DATE August 14, 1986

TIME 11 (A.M.) (P.M.)

DIRECTION: N NNE NE ENE

(E) ESE SE SSE

S SSW SW WSW

W WNW NW NNW

WEATHER Sunny, Warm

SITE Parr Canal

PHOTOGRAPHED BY:

Mike Grant

SAMPLE ID# (if applicable)



DESCRIPTION: Picture taken from northwest corner of lot. Wright Avenue runs parallel on left, End of Canal in middle on right.



## FIELD PHOTOGRAPHY LOG SHEET

DATE August 14, 1986

TIME 10:30 A.M. (P.M.)

DIRECTION: N NNE NE ENE

E ESE SE SSE

⑤ SSW SW WSW

W WNW NW NNW

WEATHER Sunny, Warm

SITE Parr Canal

PHOTOGRAPHED BY:

Mike Grant

SAMPLE ID# (if applicable)


DESCRIPTION: View along Parr Canal towards Harbor Channel and San Francisco Bay. Notice recent placement of riprap (unfinished).

DATE August 14, 1986

TIME 10:30 A.M. (P.M.)

DIRECTION: N NNE NE ENE

E ESE SE SSE

S SSW SW WSW

W WNW NW NNW

WEATHER Sunny, Warm

SITE Parr Canal

PHOTOGRAPHED BY:

Mike Grant

SAMPLE ID# (if applicable)


DESCRIPTION: View of north end of Parr Canal. Notice: riprap, storm sewer outfall, railroad spur, and geotextile membrane under crushed rock.

**APPENDIX D**

On Oct 1, 1981, David Bell + Corinne Chin met Mr. E.E. Bridgewater, V.P. of Revin-Richmond Terminal, to gain access into the vacant lot by Time Out.

We didn't find evidence of the 3 ponds that our informant mentioned. However, we spotted greyish/white fibrous clumps scattered throughout the area. There were great concentration of the matter on the eastern side of the canal (near the RR track).

Three samples were taken. The third was splitted w. Mr. Bridgewater (DEB 003).

The site is secured.

Priority ☐

(plain)

HML No. \_\_\_\_\_ To \_\_\_\_\_

# HAZARDOUS MATERIALS SAMPLE ANALYSIS REQUEST

## Part I: FIELD SECTION

(Sample is being given to RWOCB to be tested)

Collector \_\_\_\_\_ Date Sampled \_\_\_\_\_ Time \_\_\_\_\_ Hours \_\_\_\_\_

### LOCATION OF SAMPLING:

Name \_\_\_\_\_ Tel. No. \_\_\_\_\_

Address \_\_\_\_\_ Number \_\_\_\_\_ Street \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

HML No. (Lab Only)	Collector's Sample No.	Type Of Sample*	FIELD INFORMATION**
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Analysis Requested: \_\_\_\_\_

### Chain of Custody:

Signature	Title	Inclusive Dates
Signature	Title	Inclusive Dates
Signature	Title	Inclusive Dates
Signature	Title	Inclusive Dates

### Special Remarks

(e.g., duplicate sample given to company, etc.)

## Part II: LABORATORY SECTION

Received By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

Sample Allocation: ☐ HML ☐ SCBL ☐ LBL ☐ Other \_\_\_\_\_ Date \_\_\_\_\_


Analysis Required \_\_\_\_\_

\* Indicate whether sample is sludge, soil, etc.; Use back of page for additional information;

Form 8002 (5/80)

Orig.—Lab. Dup.—File Trip.—Inspector

15084-449 7-80 3M CAM



**BROWN AND CALDWELL**  
CONSULTING ENGINEERS  
ENVIRONMENTAL SCIENCES DIVISION  
1255 POWELL STREET  
EMERYVILLE, CA 94608  
PHONE (415) 428-2300

File No. 1011

Date Sampled 10/1/81  
Date Received 10/20/81  
Date Reported 11/30/81

Report To: Ms. Robin Breuer  
State of California  
Regional Water Quality Control Board  
San Francisco Bay Region  
1111 Jackson Street, Room 6040  
Oakland, California 94607

Laboratory Director

Sample Description

Fibrous Soil - 002

Fibrous Soil - 003A

Fibrous Soil - 001 (Hold, no analyses performed.)

Sample Log No.

101L1

101L2

Ion Scan: See attached report from Metallurgical Laboratories, Inc.

tos: See attached report from EMS Laboratories.

CALIFORNIA REGIONAL WATER

DEC 7 1981

QUALITY CONTROL BOARD

# METALLURGICAL Laboratories, Inc.

Chemists · Assayers · Spectrographers

4 HOWARD STREET

SAN FRANCISCO, CALIFORNIA 94103

AREA CODE 415 863-8575

## Spectrographic Analysis

(Semi-quantitative)

Examined by **Brown & Caldwell**  
1255 Powell Street  
Emeryville, California 94608  
Attention: Mr. C. K. Trent

Date **November 18, 1981**

Sample of **Products**

P. O. No. **6638**

Lab. No. **1508/1 & 2**

ANALYST →	101L #1	101L #2	SAMPLE MARK →	101L #1	101L #2
ALUMINUM	5.00 <i>300 ppm</i>	Major	SODIUM %	2.00	0.10
CHROMIUM	0.03 <i>100 ppm</i>	0.01	POTASSIUM	0.40	0.01*
COBALT	0.01 <i>2,000 ppm</i>	0.008	STRONTIUM	0.02	0.002
COPPER	0.20	0.02 <i>200</i>	ZIRCONIUM	0.01	0.006
IRON	2.50 <i>2,000 ppm</i>	0.80	BORON	0.70 <i>7000</i>	0.001
NICKEL	0.20	0.02 <i>200</i>	BARIUM	0.02 <i>200</i>	
SILVER	0.005	0.001*	RARE EARTHS	<i>600</i>	
TUNGSTEN	0.20 <i>2000</i>	0.15 <i>1500</i>	Antimony	0.06	
ZINC	0.001	0.001			
LEAD	0.08	0.35			
MANGANESE	0.001*	0.005			
NIOBIUM	Major	Major			
SILVER	0.002 <i>20</i>	0.0001			
CADMIUM	0.001	0.006			
MAGNESIUM	3.00	3.00			
CALCIUM	2.50	0.15			
THALLIUM	0.35	0.08			
BISMUTH					

**RECEIVED**

NOV 19 1981

BROWN AND CALDWELL

METALLURGICAL LABORATORIES, INC.

LESS THAN

*W. P. Davis*

Asbestos Bulk Sample Optical Analysis

Client Brown & Caldwell Date Nov. 2, 1981 P.O. No. 6649N

Laboratory I.D. #	4106-A	4106-B			
Sample Description	101L1	101L2			
Sample Appearance	Dark Brown, Fibrous, Inhomogeneous	Tan to Brown, Fibrous, Inhomogeneous			
Sample Treatment	Crushed, Mixed	Mixed, Ground			
Asbestos Present Type & Percent	Amosite Chrysotile Total 11% ± 3%	Amosite 9% ± 3%			
Other Fibrous Materials Present	Mineral Wool	None			
Non-Fibrous Materials Present	Diatoms Granular Minerals	Granular Minerals			



PRIORITY ☒ ( )

HML No. 8912  
To \_\_\_\_\_

HAZARDOUS MATERIALS SAMPLE ANALYSIS REQUEST

FIELD SECTION

Collector Dick Burgard Date Sampled 1-18-84 Time \_\_\_\_\_ Hours \_\_\_\_\_  
LOCATION OF SAMPLING: Parr Richmond Terminal, Parr Canal Site Tel. No. \_\_\_\_\_  
Address Third and Wright, Richmond 94805  
Number \_\_\_\_\_ Street \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

No. \_\_\_\_\_ Collector's Sample No. \_\_\_\_\_ Type Of Sample\* \_\_\_\_\_  
(If Only) \_\_\_\_\_  
2 DB 001 soil & fiber

FIELD INFORMATION\*\*

Requested: Asbestos Analysis

Custody: Dick Burgard Signature \_\_\_\_\_ Title WMS II Date 1-18-84 - 1-18-84  
Carol Woronow Signature \_\_\_\_\_ Title LAB ASST Date 1-18-84  
Signature \_\_\_\_\_ Title \_\_\_\_\_ Inclusive Dates \_\_\_\_\_  
Signature \_\_\_\_\_ Title \_\_\_\_\_ Inclusive Dates \_\_\_\_\_  
Signature \_\_\_\_\_ Title \_\_\_\_\_ Inclusive Dates \_\_\_\_\_

(e.g., duplicate sample given to company, etc.)

LABORATORY SECTION

Analyst Tammy Title PHC II Date 7-18-84  
Location: ☐ HML ☐ SCBL ☐ LBL ☐ Other \_\_\_\_\_  
Required (Sent to A/HU)

**URGENT**

Page \_\_\_\_ of \_\_\_\_

2. Region ☐ District ☐

3. Date Submitted 1-18-84

S. Phone No. 40-310

I.D. No.				Rpt. No.		Yr.	
1	2	3	4	5	6	7	8

205.2

Date Laboratory Results Desired: 1-84

**Sample Information:**

Name of Establishment PARR Richmond Term

Address THIRD AND WRIGHT ST. RICHMOND, CALIF

**No.  
Lab.  
Only**Field  
No.Date  
Coll.Type of Sample  
See Below:

## Volume

### Field Information

## Analysis Requested

47059

ΔΔ!

-8

SI / F EIL

En

ASBEST S

Serial = M; Bag = B; Settled Dust = S; Grab Sample = G; Impinger = I; Bubbler = Bu; ESP = E; Filter Paper = F; Other - Write In.

# LABORATORY REPORT

TO: OH ☒  
DIS ☐

Region ☐  
District ☐

Name HML

(Pick-Up)

1. DIS Inspection/I.H. Investigation Identification:

I. D. No.	Rpt. No.	Yr.

2. Name of Establishment Parr Richmond Terminal

3. Date This Report:

Address Third and Wright St., Richmond, CA

Mo.	Day	Yr.
01	31	84

## 4. Laboratory Results

Lab. No. <small>For Lab. Use Only</small>	Field No.	Laboratory Results
40089	DB 001	Contains 45 percent (plus or minus 15 percent) asbestos.

RECEIVED

FEB 2 1984  
Department of Industrial Hygiene  
CALIFORNIA  
OSHA

Signatures of Chemists Involved

6. Signature of Supervising Chemist


William B. Smith, 1/27/84.

Steven B. Hayman  
R/S



HAZARDOUS WASTE

SURVEILLANCE AND COMPLIANCE REPORT



DATE 3-5-84

FIRM NAME Levin Richmond Terminal SITE CLASSIFICATION ☐ I ☐ II-1 ☐ II-2 ☐ III  
Parr Canal Site  
ADDRESS 402 Wright Ave. ☐ Other \_\_\_\_\_  
Richmond, Ca 94804 SITE PERMIT NO. CAX 000015263

Purpose: This inspection was conducted to oversee collection of core samplings immediately offshore from the site and to check on security of the site.

Background: This site was last inspected on Jan. 24, 1984 by Dick Burgard and Dwight Hoenic. No violations in site maintenance or security were observed during that inspection.

Samples collected from the Parr Canal Site had:

DB002 34.8 ppm DDT ( $\mu\text{g/g}$ )  
DB003 2.4 ppm DDT

On January 18, 1984 a sample was collected from the Parr Canal site for Asbestos analysis. Results showed 45% Asbestos  $\pm$  15%.

Persons Present: Bill Frizzell, Harding Lawson  
Dick Burgard, TSCD

Sampling Activity: Five cores were sunk into Bay sediments 12 ft cores were obtained --- (four sections, 3 foot lengths) cores were very soft --- could not extrude and provide splits, on site. We agreed to have the cores sent to EAL to be extruded and split.

Observations: The fence at the North End of the 402 Wright Sight is down. The fence is being repaired, however, a 24 hour guard is posted to prevent access by unauthorized persons. This is an acceptable alternative.

INSPECTOR

Dick Burgard

DATE

3-6-84

LABORATORY REPORT  
Chlorinated Pesticides and PCB's

Collector's Name Dickie Brangard Date Received by Laboratory 1/24/84  
Sampling Location Levin Richmond Terminal Collector's Sample # DB002 to  
pollutant site, 8th & Whittier, Richmond. DB003

Analytical Procedure: Sample(s) were extracted with organic solvents. Constituents were determined by gas chromatography with electron capture detector according to HML Methods (refer to AOAC, 13th Ed., 29.013).

HML #	8947	8948					Detection Limit/Units
Collector's Sample #	DB002	DB003					
*Aldrin							0.1
*a-BHC							0.1
*b-BHC							0.1
*c-BHC							0.1
*g-BHC (Lindane)							0.1
*Chlordane							0.2
*4,4'-DDE	2.7 µg/g	-					0.2
*4,4'-DDD	1.1 µg/g	-					0.2
*4,4'-DDT	31 µg/g	2.4 µg/g					0.3
*Dieldrin							0.2
*Endosulfan I							0.2
*Endosulfan II							0.2
*Endosulfan sulfate							0.3
*Endrin							0.2
*Endrin aldehyde							0.2
*Heptachlor							0.1
*Heptachlor epoxide							0.1
*Toxaphene							1.0
*PCB's (calc. as )							
OP-DDT	1.8 µg/g	-					
Methoxychlor							0.1
PCNB							0.3
Perthane							0.2
Trithion							0.5

\*Constituents on EPA priority pollutant list

Note: (-) = Not detected  
(blank) = Not determined

Analyst's Signature

Paula Chang

Signature of Supervising Chemist

Norman Tor

2/10/84  
(Date)

2/10/84  
(Date)


A Report Prepared for


Levin Richmond Terminal Corporation  
402 Wright Avenue  
Richmond, California 94804

SITE CHARACTERIZATION AND  
REMEDIAL ACTION PLAN  
PARR CANAL SITE  
RICHMOND, CALIFORNIA

HLA Job No. 8429,003.02

by

  
William F. Frizzell,  
Civil Engineer - 33013

  
James C. Davies,  
Principal Engineer

Harding Lawson Associates  
7655 Redwood Boulevard, P.O. Box 578  
Novato, California 94948  
415/892-0821

June 27, 1985

Appendix A

LABORATORY REPORTS

RESULTS OF SOILS ANALYSES - TEST PITS



3. 1984

King Lawson Associates

Report #2501

Page 1

Units : All results are given in ug/g or ppm

#	HL ID	DDE	opDDT	ppDDT	ppDDT	DDT <i>DDT summation</i>	PCE
1-1	#1 @ 1'	0.13	ND(0.05)	0.35	0.07	.35	ND(1)
1-2	#1 @ 2'	0.15	ND(0.05)	0.72	0.08	.93	ND(1)
1-3	#1 @ 3'	0.12	0.11	0.17	0.29	.69	1.1
1-3 Dup	#1 @ 3'	0.15	0.12	0.22	0.35	.84	1.1
1-4	#2 @ 1'	9.3	1.2	2.4	9.0	43.5	12
1-5	#2 @ 2'	ND(0.5)	ND(0.5)	2.4	ND(0.5)	2.4	ND(1)
1-6	#2 @ 3'	0.05	0.05	0.09	0.14	.32	ND(1)
1-7	#2 @ 4'	0.08	ND(0.05)	0.05	ND(0.05)	.15	ND(1)
1-8	#3 @ 1'	19	11	58	35	133	55
1-8 Dup	#3 @ 1'	15	5.7	54	21	96.7	70
1-9	#3 @ 2'	0.63	ND(0.5)	1.4	0.48	2.49	12
1-10	#3 @ 3'	0.24	ND(0.5)	0.72	0.40	1.36	11
1-11	#3 @ 4'	0.10	ND(0.05)	0.48	0.10	.69	12
1-12	#4 @ 1'	0.41	0.62	0.41	2.0	3.44	11
1-13	#4 @ 2'	1.9	2.4	1.7	5.5	11.4	11
1-14	#4 @ 3'	ND(0.05)	ND(0.05)	0.08	0.11	.19	ND(1)

ND = none detected, detection limits in parentheses

Comments : All PCE found was identified as Aroclor 1254. In some cases higher detection limits are given due to interferences from PCB or other chlorinated compounds.

Submitted By :

*Michael Lynch*

Michael Lynch  
Technical Director

RESULTS OF SOILS ANALYSES - BORINGS B1 through B10

# EAL Corporation



2030 Wright Avenue  
Richmond, California 94804  
(415) 235-2633  
(TWX) 910-382-8132

## ANALYSIS REPORT

HARDING LAWSON ASSOCIATES  
P O BOX 578  
NOVATO CA 94947  
ATTENTION: BILL FRIZZELL

DATE: 5-17-84  
Samples Received: 5-11-84  
EAL W.O. No. 48-5800  
Purchase Order No. NONE

SAMPLE IDENTIFICATION			P,P' DDD	P,P' DDE	P,P' DDT
EAL	CUSTOMER		PPM	PPM	PPM
255-105-1	B-1	2.5-3.0'	<0.1	<0.1	0.3
255-105-2	B-1	4.0-4.5'	0.3	0.1	0.2
255-105-3	B-2	1.0-1.5'	<0.1	<0.1	<0.1
255-105-4	B-2	3.5-4.0'	<0.1	<0.1	<0.1
255-105-5	B-3	1.0-1.5'	<0.1	<0.1	<0.1
255-105-6	B-3	3.0-3.5'	<0.1	<0.1	<0.1
255-105-7	B-4	0.5-1.0'	0.2	<0.1	0.6
255-105-8	B-4	5.0-5.5'	<0.1	<0.1	<0.1
255-105-9	B-5	1.0-1.5'	5.2	9.9	140
255-105-10	B-5	3.0-3.5'	<0.1	<0.1	<0.1
255-105-11	B-6	0.5-1.0'	0.2	1.2	0.7
255-105-12	B-6	3.0-3.5'	1.1	0.7	5.9
255-105-13	B-7	2.0-2.5'	6.0	1.4	36
255-105-14	B-7	4.0-4.5'	0.1	<0.1	0.4
255-105-15	B-8	1.0-1.5'	<0.1	<0.1	<0.1
255-105-16	B-8	4.0-4.5'	<0.1	<0.1	<0.1
255-105-17	B-9	1.0-1.5'	<0.1	<0.1	1.6
255-105-18	B-9	4.0-4.5'	<0.1	<0.1	<0.1
255-105-19	B-10	1.0-1.5'	0.1	<0.1	0.6
255-105-20	B-10	4.0-4.5'	<0.1	<0.1	<0.11

George E. Dunstan  
Program Manager

**RESULTS OF SOILS ANALYSES - BORINGS A THROUGH J**

HARDING LAWSON ASSOC.

APR 10 1985

**Thermo Electron**  
CORPORATION

# EAL Corporation

2030 Wright Avenue  
Richmond, California 94804  
(415) 235-2633  
(TWX) 910-382-8132


Harding Lawson Associates  
P.O. Box 578  
Novato, CA 94947  
Attn: Bill Frizzell

April 9, 1985  
Samples Received: 2/22/85  
EAL W.O. No.: 485800-255-126

## ANALYSIS REPORT (Revised)

Sample Identification EAL	Customer	Lead (mg/kg)	p,p'DDT (mg/kg)	p,p'DDE (mg/kg)	p,p'DDD (mg/kg)
255-126-1	A @ 1.5	70	<0.1	<0.1	<0.1
255-126-2	A @ 5.5	11	<0.1	<0.1	<0.1
255-126-3	B @ 0.0	810	0.73	0.11	<0.1
255-126-4	B @ 5.0	13	0.12	<0.1	<0.1
255-126-5	C @ 1.0	78	0.10	<0.1	<0.1
255-126-6	C @ 5.5	15	<0.1	<0.1	<0.1
255-126-7	D @ 2.0	770	<0.1	<0.1	<0.1
255-126-8	D @ 5.5	29	<0.1	<0.1	<0.1
255-126-9	E @ 1.0	1,500	0.26	0.15	0.89
255-126-10	E @ 5.5	16	<0.1	<0.1	<0.1
255-126-11	F @ 1.0-2.5	56	0.44	0.13	0.63
255-126-12	F @ 3-4.5	120	0.41	0.14	1.9
255-126-13	G @ 0.0	110	0.89	0.23	0.32
255-126-14	G @ 3.5	140	240	10	49
255-126-15	H @ 1-2.5	400	23	3.5	3.5
255-126-16	H @ 5-6.5	180	4.4	0.78	1.1
255-126-17	I @ 1-2.5	1,900	8.9	0.77	1.6
255-126-18	I @ 6-7.5	110	0.21	0.13	0.69
255-126-19	J @ 1-2.5	81	350	19	30
255-126-20	J @ 5-6.5	33	1.5	<0.1	0.16

Sample Identification EAL	Customer	o,p DDT (mg/kg)	o,p DDE (mg/kg)	o,p DDD (mg/kg)
255-126-14	G @ 3.5	30	1.6	20
255-126-15	H @ 1 - 2.5	2.7	0.38	0.65
255-126-16	H @ 5 - 6.5	0.70	<0.1	0.26
255-126-17	I @ 1 - 2.5	0.67	<0.1	0.35
255-126-19	J @ 1 - 2.5	68	2.4	8.7

  
George E. Dunstan  
Manager, Hazardous Waste Programs

GED/dss

RESULTS OF WASTE EXTRACTION TESTS



ANATEC

281/006 6779

- 2 -

June 10, 1985

Results of the testing are summarized in Table 1. The results are reported as "mg/L in the WET extract." The results could be converted to a dry weight basis by multiplying the WET-soluble result by 10.

If you have any questions regarding this work, please contact us.

Submitted by:

Robert P. Di Rienzo  
Staff Chemist

Approved by:

Stephen F. Nackord  
Laboratory Supervisor

/co


Table 1. Summarized Analytical Results for "Parr Canal"  
Samples Submitted on May 28, 1985

Parameter	Descriptor, Lab No., and Results <sup>1</sup> (mg/L)			
	Parr Canal			
	E @ 1.0 ft 2-12-85 (6779-1)	G @ 3.5 ft 2-12-85 (6779-4)	I @ 1.0-2.5 ft 2-13-85 (6779-2)	J @ 1.0-2.5 ft 2-14-85 (6779-3)
Lead	27	--	42	--
4,4'-DDD	--	<0.01	--	<0.01
4,4'-DDE	--	<0.01	--	<0.01
4,4'-DDT	--	<0.01	--	<0.01

<sup>1</sup>Concentration in Waste Extraction Test extract.

RESULTS OF CANAL SEDIMENT ANALYSES





ANATEC

281/005 Log 6719

- 5 -

June 6, 1985

Table 2. Total CAM Metals Test Results for  
Parr Canal Sediment Samples

Parameter	Method Detection Limit (mg/Kg)	Descriptor, Lab No. and Results (mg/Kg) <sup>1</sup>				
		SA (6719-1)	SB (6719-2)	SC (6719-3)	SD (6719-4)	SE (6719-5)
Antimony	20	ND <sup>2</sup>	ND	ND	ND	ND
Arsenic	0.5	2.6	4.5	3.1	7.3	3.1
Barium	20	40	80	60	120	40
Beryllium	10	ND	ND	ND	ND	ND
Cadmium	10	ND	ND	ND	ND	ND
Chromium	5	41	53	53	41	53
Cobalt	20	ND	ND	ND	ND	ND
Copper	10	40	55	60	30	55
Lead	20	230	140	130	80	120
Mercury	2	ND	ND	ND	ND	ND
Molybdenum	20	ND	ND	ND	ND	ND
Nickel	20	20	40	40	40	30
Selenium	10	ND	ND	ND	ND	ND
Silver	50	ND	ND	ND	ND	ND
Thallium	50	ND	ND	ND	ND	ND
Vanadium	10	25	45	45	30	40
Zinc	10	170	190	160	50	130

<sup>1</sup>Wet weight basis.<sup>2</sup>ND--Analyte not detected in sample at or above listed method detection limit.



ANATEC

281/005 Log 6719

- 6 -

June 6, 1985

Table 3. Priority Pollutant Organochlorine Pesticides and Polychlorinated Biphenyls Test Results for Parr Canal Sediment Samples

Compound	Method	Descriptor, Lab No. and Results (mg/Kg) <sup>1</sup>				
	Detection Limit (mg/Kg)	SA (6719-1)	SB (6719-2)	SC (6719-3)	SD (6719-4)	SE (6719-5)
Organochlorine Pesticides						
Aldrin	1	ND <sup>2</sup>	ND	ND	ND	ND
alpha-BHC	1	ND	ND	ND	ND	ND
beta-BHC	1	ND	ND	ND	ND	ND
gamma-BHC	UTD <sup>3</sup>	--	--	--	--	--
delta-BHC	1	ND	ND	ND	ND	ND
Chlordane	20	ND	ND	ND	ND	ND
4,4'-DDD	1	2	9	2	ND	4
4,4'-DDE	1	ND	ND	ND	ND	ND
4,4'-DDT	1	ND	5	ND	ND	ND
Dieldrin	1	ND	ND	ND	ND	ND
alpha-Endosulfan	1	ND	ND	ND	ND	ND
beta-Endosulfan	1	ND	ND	ND	ND	ND
Endosulfan sulfate	1	ND	ND	ND	ND	ND
Endrin	1	ND	ND	ND	ND	ND
Endrin aldehyde	UTD	--	--	--	--	--
Heptachlor	1	ND	ND	ND	ND	ND
Heptachlor epoxide	1	ND	ND	ND	ND	ND
Toxaphene	30	ND	ND	ND	ND	ND
Polychlorinated Biphenyls						
PCB-1016	10	ND	ND	ND	ND	ND
PCB-1221	10	ND	ND	ND	ND	ND
PCB-1232	10	ND	ND	ND	ND	ND
PCB-1242	10	ND	ND	ND	ND	ND
PCB-1248	10	ND	ND	ND	ND	ND
PCB-1254	10	ND	ND	ND	ND	ND
PCB-1260	10	ND	ND	ND	ND	ND

<sup>1</sup>Wet weight basis.

<sup>2</sup>ND--Analyte not detected in sample at or above listed method detection limit.

<sup>3</sup>UTD--Unable to determine; reference material not available.

Note: No other Hall detector-responsive compounds were observed in the sample extracts.

RESULTS OF GROUND-WATER ANALYSES

Harding Lawson Associates  
EAL W.O. No.: 455300-255-126

March 11, 1985

Sample Identification		259-126-45	259-126-46	259-126-47
Analysis	Units	Composite A+B	Composite C+D	Composite G+H
Dissolved Antimony	mg/L	<0.4	<0.2	<0.2
Dissolved Arsenic	mg/L	0.006	0.005	0.01
Dissolved Barium	mg/L	0.14	0.35	0.16
Dissolved Beryllium	mg/L	<0.001	<0.001	<0.001
Dissolved Cadmium	mg/L	<0.005	<0.005	<0.005
Dissolved Total Chromium	mg/L	0.016	0.014	0.018
Dissolved Cobalt	mg/L	0.22	<0.005	<0.005
Dissolved Copper	mg/L	0.014	<0.001	0.004
Dissolved Lead	mg/L	<0.05	<0.05	<0.05
Dissolved Mercury	mg/L	<0.0005	<0.0005	<0.0007
Dissolved Molybdenum	mg/L	<0.1	<0.04	0.16
Dissolved Nickel	mg/L	0.04	<0.02	0.03
Dissolved Selenium	mg/L	0.007	0.007	0.006
Dissolved Thallium	mg/L	0.2	<0.05	<0.05
Dissolved Vanadium	mg/L	<0.003	<0.003	<0.003
Dissolved Zinc	mg/L	0.048	0.034	0.024

Sample Identification		259-126-48	259-126-49
Analysis	Units	I	J
Dissolved Antimony	mg/L	<0.2	<0.2
Dissolved Arsenic	mg/L	0.007	<0.005
Dissolved Barium	mg/L	0.12	0.12
Dissolved Beryllium	mg/L	<0.001	<0.001
Dissolved Cadmium	mg/L	<0.005	<0.005
Dissolved Total Chromium	mg/L	0.016	0.019
Dissolved Cobalt	mg/L	<0.005	<0.005
Dissolved Copper	mg/L	0.002	0.004
Dissolved Lead	mg/L	<0.05	<0.05
Dissolved Mercury	mg/L	<0.0005	<0.0005
Dissolved Molybdenum	mg/L	<0.04	0.09
Dissolved Nickel	mg/L	<0.02	0.06
Dissolved Selenium	mg/L	<0.005	<0.005
Dissolved Thallium	mg/L	<0.05	<0.05
Dissolved Vanadium	mg/L	<0.003	<0.003
Dissolved Zinc	mg/L	0.016	0.048

RESULTS OF PARR CANAL WATER ANALYSES



ANATEC

281/008 Log 6792

- 2 -

June 11, 1985

Table 1. Summarized Results for Parr Canal Bay Water Sample  
(ALI 6792-1)

<u>Parameter</u>	<u>Concentration (mg/L)</u>
Antimony, & compounds	<0.2
Arsenic, & compounds	<0.01
Barium, & compounds	<0.2
Beryllium, & compounds	<0.005
Cadmium, & compounds	<0.005
Chromium (III), & compounds	<0.01
Cobalt, & compounds	<0.01
Copper, & compounds	<0.01
Lead, & compounds	<0.02
Mercury, & compounds	<0.0005
Molybdenum, & compounds	<0.04
Nickel, & compounds	<0.02
Selenium, & compounds	<0.01
Silver, & compounds	<0.01
Thallium, & compounds	<0.05
Vanadium, & compounds	<0.02
Zinc, & compounds	0.14